

Technical Service Notification

This service notification provides information to Veeder-Root service network and technicians regarding recently released Quick Troubleshooting Guides

1.0 Purpose

Veeder-Root recently released Quick Troubleshooting Guides on various Red Jacket and ATG subjects. They are posted on Veeder-Root Web Site.

TITLE	PART NO.
Red Jacket Petroleum and AG STP - Pressure Loss Quick Troubleshooting Guide	577014-334
FX Mechanical Leak Detectors Quick Troubleshooting Guide	577014-340
Maxxum Big-Flo 6" STP - Pressure Loss Quick Troubleshooting	577014-341
The Red Jacket STP - Pressure Loss Quick Troubleshooting Guide	577014-342
The Red Jacket UMP Quick Troubleshooting Guide	577014-343
Thermal Contraction Quick Troubleshooting Guide	577014-345
Discriminating Dispenser Pan and Sump Sensors Quick Troubleshooting Guide	577014-346
DPLLD, PLLD, or WPLLD Quick Troubleshooting Guide	577014-347
Magnetostrictive Probes Quick Troubleshooting Guide	577013-348
Universal Sensor / Probe Interface Module (USM) for TLS-450PLUS Quick Troubleshooting Guide	577014-349

To review these Quick Troubleshooting Guides go to:

<http://www.veeder.com/us/support/veeder-root-redjacket-technical-documentation>

2.0 Further Information

For questions or to receive copies of available documentation, please contact technical support at technicalsupport@veeder.com.