VEEDER-ROOT

Software Release Version 10.H
TLS-450PLUS and TLS4 Series Consoles

Purpose

This document announces the release of version 10.H software for the TLS-450PLUS and TLS4 series consoles.

▶ Performance Enhancements

HydrX™ Fuel Conditioning System

- Contextual help screens for all HydrX features.
- Updates to RS-232 serial commands.

Web Browser Console Login Change

- As part of ongoing network security improvements, the console CPU Serial Number must be used as the Password to access the console via the web interface, if an Administrator account has not yet been created.

- Before updating the console software to version 10.H, refer to the Veeder-Root Technical Support Notification, dated March 28, 2023, for detailed instructions on how to add an Administrator account and locate the console CPU Serial Number: **veeder.com/us/enhanced-tls-450plus-tls4-series-web-interface-login**.

Ongoing Improvements

- Version 10.H includes miscellaneous bug fixes and updates.

▶ Software Upgrade Download – TLS-450PLUS and TLS4 Series Consoles

Software upgrades are always free to download on our website at **veeder.com/us/software-downloads**.

▶ Documentation

For more information on the software download process, refer to **TLS-450PLUS/TLS4 Operator's Manual (577014-110)**.

Support

📞	**+1.814.695.4476** — Customer Service (*International)*
📞	**+1.800.873.3313** — *Customer Service*
📞	**+1.800.323.1799** — *Technical Support*
📠	**+1.800.234.5350** — *Customer Service*
✉	customerservice@veeder.com

veeder.com