GILBARCO
VEEDER-ROOT

MDE-3910A
**Adhesive Hook and Loop Fastener Squares
for POS System Customer Display
PA0327XXXX
April 2003**

Installation Instructions

Purpose

This document provides instructions on attaching the 1-inch adhesive hook and loop fastener squares to the base of the point of sale (POS) system customer display (PA0327XXXX).

The hook and loop fastener squares help to ensure that the POS system customer display (PA0327XXXX) does not tip over when the display is moved or jarred.

Tools

No special tools are required.

Procedure

CAUTION

Customer display should be fastened to counter top with screws, or by attaching hook and loop fastener squares and placing display base under monitor base or cash drawer for additional support. Warranty may be voided if customer display is not secured in this manner and display is damaged as a result of tipping over.

1 Carefully lay the customer display on its side, exposing the underside of the display base.

2 Peel the backing off one of the four hook and loop fastener squares and firmly apply the adhesive side to a corner on the underside of the customer display base. Refer to "Correct placement of adhesive hook and loop fastener squares" on the back of these instructions.

3 Repeat Step 2 for each of the remaining hook and loop fastener squares.

Correct placement of adhesive hook and loop fastener squares

Hook and Loop
Fastener Square

Hook and Loop
Fastener Square

Underside of
Customer Display
Base

S0002281

Hook and Loop
Fastener Square

Hook and Loop
Fastener Square

GILBARCO
VEEDER-ROOT