



Software Release Version 10.N

TLS-450PLUS and TLS4 Series Consoles



This document announces the release of version 10.N software for the TLS-450PLUS and TLS4 series consoles.

Ongoing Improvements

Digital Pressure Line Leak Detection & Intelligent Pump Control

- Version 10.N addresses an update required in consoles equipped with Digital Pressure Line Leak Detection (DPLLD) in the TLS-450PLUS, when using Intelligent Pump Control (IPC) with manifolded lines and Active Switchover.
- If there are any questions regarding this required update, please contact Technical Support for assistance.



▶ Software Upgrade Download – TLS-450PLUS, TLS4 Series Consoles

Software upgrades are always free to download on our website at veeder.com/us/software-downloads.

Documentation

For more information on the software download process, refer to TLS-450PLUS/TLS4 Operator's Manual (577014-110).

Support



+1.814.695.4476 — Customer Service (*International*)

+1.800.873.3313 — Customer Service

+1.800.323.1799 — Technical Support

+1.800.234.5350 - Customer Service

customerservice@veeder.com

