


## Revision History

### MDE-5132B PX60 Passport® Standalone Manager Workstation Using the RV042 Firewall Router

Tabulated below are the technical changes from MDE-5132A to MDE-5132B.


<b>MDE-5132B Print Copy Page Location</b>	<b>Changes</b>	<b>Rev. Date</b>
Across the document	<ul style="list-style-type: none"><li>• Updated the revision alphabet.</li><li>• Updated the current month/year.</li><li>• Added the “Obsolete” watermark.</li></ul>	06/08/20 06/08/20 06/08/20

## 1 Standalone Manager Workstation (MWS) and Peripherals




Note: You should have all the equipment parts shown in illustration.


## 2 Combined Cashier Workstation (CWS)/MWS Components to the Server



## 3 Standalone MWS Connection Matrix



## 4 Standalone MWS Peripheral Power Cables



Notes:

- Only a Gilbarco Authorized Contractor (ASC) should connect Passport equipment to the UPS and turn on AC power.
- Connect only Passport system equipment to the UPS. Do not power any other equipment from the UPS.