

Revision History


MDE-5101B Passport Combined Cashier/Manager Workstation Using the RV042 Firewall Router

Tabulated below are the technical changes from MDE-5101A to MDE-5101B.

MDE-5101B Print Copy Page Location	Changes	Rev. Date
Across the document	• Updated the revision alphabet. • Updated current month/year. • Added “Obsolete” watermark.	06/04/20 06/04/20 06/04/20

1


Combined Cashier Workstation/Manager Workstation (CWS/MWS) and Peripherals



Note: You should have all the equipment parts shown in illustration.


2

Combined CWS/MWS Components to the Server




3

Combined CWS/MWS Connection Matrix



4

Combined CWS/MWS Peripheral Power Cables



Notes:
• Only a Gilbarco-trained Authorized Service Contractor (ASC) should connect Passport equipment to the UPS and turn on AC power.
• Connect only Passport system equipment to the UPS. Do not power any other equipment from the UPS.