

Software Release Version 10.P

TLS-450PLUS and TLS4 Series Consoles

Purpose

This document announces the release of version 10.P software for the TLS-450PLUS and TLS4 series consoles. Veeder-Root always recommends downloading the most up-to-date software to ensure optimal site and equipment performance.

► Performance Enhancements

In-Station Diagnostics (ISD) for California

- Update to ISD Daily Report Details

Wireless 4 (Europe Only)

- Context Help added for English, German, French, and Spanish

HydrX™ Fuel Conditioning System

- Reduced HydrX alarms and warnings related to HydrX Out Alarms, Low & High Temperature Warnings, and Water Level Warnings
- Improved interaction between Static Leak Detection (SLD), Continuous Statistical Leak Detection (CSLD), Digital Pressurized Line Leak Detection (DPLLD), and HydrX operation
- Context Help added for English and French

Ongoing Improvements

- Version 10.P includes miscellaneous bug fixes and updates



► Software Upgrade Download – TLS-450PLUS, TLS4 Series Consoles

Software upgrades are always free to download on our website at veeder.com/us/software-downloads.

► Documentation

For more information on the software download process, refer to [TLS-450PLUS/TLS4 Operator's Manual \(577014-110\)](#).

Support

-  +1.814.695.4476 – Customer Service (*International*)
-  +1.800.873.3313 – Customer Service
-  +1.800.323.1799 – Technical Support
-  +1.800.234.5350 – Customer Service
-  customerservice@veeder.com

