

# Firmware Release Updates

## IQ2 Smart Controller


**Version 4.05 firmware for the Red Jacket® IQ2 Smart Controller is now available.** The 4.05 version includes important updates that improve STP protection settings to streamline operations.

### ► Performance Enhancements

#### Red Jacket IQ2 Smart Controller

**IQ2 Firmware 4.05** is currently the **minimum version suggested** for any application, and include the following improvements:

- Improved hook switch response.
- Adjusted relay set points for 3phase 50Hz STP with the following UMP:
  - UMP75U17
  - UMP150U17
  - UMP400U17
  - UMP500J17
  - FE STP150C
  - FE STPM200C







### ► IQ2 Firmware Upgrade Download

To download the latest software updates, please visit: [veeder.com/us/software-downloads](https://veeder.com/us/software-downloads).

### ► Documentation

For additional details on software downloads, refer to the [IQ2 Control Box Installation and Operation Manual \(577014-500\)](#).

### Support

-  +1.814.695.4476 — Customer Service (International)
-  +1.800.873.3313 — Customer Service
-  +1.800.323.1799 — Technical Support
-  [customerservice@veeder.com](mailto:customerservice@veeder.com)

