

Firmware Release Updates

IQ2 Smart Controller


Version 4.07 firmware for the Red Jacket® IQ2 Smart Controller is now available.

Performance Enhancements

Red Jacket IQ2 Smart Controller

IQ2 Firmware 4.07 is currently the **minimum version suggested to operate IQ2**, for any application, and includes the following improvements:

- Updated the Helper Mode Threshold value to be 20%. The default value was 60%.
- Improved manifolded STP operations



► IQ2 Firmware Upgrade Download

To download the latest software updates, please visit: veeder.com/us/software-downloads.

► Documentation

For additional details on software downloads, refer to the [IQ2 Control Box Installation and Operation Manual \(577014-500\)](#).

Support

-  +1.814.695.4476 – Customer Service (*International*)
-  +1.800.873.3313 – Customer Service
-  +1.800.323.1799 – Technical Support
-  customerservice@veeder.com

