

# Software Release Version 9.Y

## TLS-450PLUS and TLS4 Series Consoles

### Purpose

This document announces the release of version 9.Y software for the TLS-450PLUS and TLS4 series consoles.



### ► Performance Enhancements

Updates SD card firmware to prevent a rare condition where the SD card becomes inoperable. **Veeder-Root recommends upgrading to version 9.Y for any TLS-450PLUS or TLS4 series consoles shipped between April 1, 2021 – August 1, 2021.**

### ► Software Upgrade Kit – TLS-450PLUS, TLS4 Series Consoles

Software upgrades are always free to download on our website at [veeder.com/us/software-downloads](https://veeder.com/us/software-downloads).

Software upgrades can also be ordered on a USB Flash drive at no charge by ordering the software kit part number in the table below.

Part Number	Description	List Price
330020-744	TLS-450PLUS, TLS4 Series Operating Software Upgrade	No Charge

### ► Documentation

Manual information is available at [veeder.com/us/technical-document-library](https://veeder.com/us/technical-document-library).

### Support

-  **1.800.323.1799** – Technical Support
-  **1.800.873.3313** – Customer Service
-  **1.800.234.5350** – Customer Service
-  [customerservice@veeder.com](mailto:customerservice@veeder.com)

