

Product Update Notification

TLS-350 Console Software

Overview

The memory chips used on the existing generation of the TLS-350 software ROM board has been impacted by supply chain challenges. To mitigate extended delivery times, Veeder-Root has identified an additional memory chip supplier. This supplier offers a ROM board that is compatible with ECPU2 Gen2 boards. The software embedded on this new design is identical to the previous 136/336 release on the older version of the ROM board and has no impact on operational performance.

New ROM Board




Previous ROM Board



► Targeted Market

North America Only



Scheduled Release Timing

The new design ROM Board is currently being tested and software version 136/336 will be released in the coming weeks. Lead times for the California market cannot be determined at this time due to California Air Resource Board (CARB) testing requirements of the new design.


As of **January 25, 2023**, Veeder-Root started shipping the new software version 136/336 to all customers outside of California.


Order Details

If a replacement ROM board is required, software version 136/336 (updated ORVR ISD tables) must be ordered. Please specify 0346336-1xx or 0346136-1xx software on your order and send it to Customer Service at customerservice@veeder.com.

125 Powder Forest Drive • PO Box 2003 • Simsbury, CT 06070 • ©2023 Veeder-Root • P/N 576047-480







+1.800.323.1799 — Technical Support



+1.800.234.5350 — Customer Service

<u>customerservice@veeder.com</u>

