

FIELD SERVICE BULLETIN

Bulletin: RJ-23-33

Revision: E

Product: Submersible Pumps Reference: Submerged in Water

Date: October 1991

Red Jacket is aware of the fact that submersible pumps are being installed in tanks that employ water as a ballast. This definitely IS NOT a recommended practice. Uncoated cast iron parts may rust and be discharged into the product line which creates the potential for premature equipment failures. Red Jacket cannot be responsible for pump failures resulting from being submerged in water.

If there are any questions or comments concerning this bulletin, please call the TECH LINE at 1-800-262-7539 and consult with an applications technician. Thank you for choosing Red Jacket pumps.

Please keep this bulletin for your future reference.