

Software Release Version 10.F

TLS-450PLUS and TLS4 Series Consoles

Purpose

This document announces the release of version 10.F software for the TLS-450PLUS and TLS4 series consoles.

► Performance Enhancements

HydrX™ Fuel Conditioning System – New Feature Supported

- The HydrX Fuel Conditioning System no longer requires a Fuel Conditioning Controller (FCC) with the TLS-450PLUS console. HydrX is now supported with software version 10.F or higher on the TLS-450PLUS console or TLS4 console with a TLS-XB Expansion Box *.
- This new feature integrates all functionality of the FCC into the console, which enables remote access to HydrX status, configuration, alarms, and reports.
- Existing HydrX users can upgrade to 10.F to take advantage of these features without additional hardware in most cases.

Ongoing Improvements

- Version 10.F includes miscellaneous bug fixes and updates.



► Software Upgrade Download – TLS-450PLUS, TLS4 Series Consoles

Software upgrades are always free to download on our website at veeder.com/us/software-downloads.

► Documentation

For more information on the software download process, refer to [TLS-450PLUS/TLS4 Operator's Manual \(577014-110\)](#).

* TLS4B is not compatible with HydrX.

Support

-  +1.814.695.4476 – Customer Service (*International*)
-  +1.800.873.3313 – Customer Service
-  +1.800.323.1799 – Technical Support
-  +1.800.234.5350 – Customer Service
-  customerservice@veeder.com

