



1 Cashier Workstation and Peripherals




Note: You should have all the equipment parts shown in illustration.


2 Cashier Workstation Components to the Client



3 Combined Cashier/Manager Workstation Connection Matrix



4 Combined Cashier/Manager Workstation Peripheral Power Cables



Notes:
 • Only a Gilbarco® Authorized Service Contractor (ASC) should connect Passport equipment to the UPS and turn on AC power.
 • Connect only Passport system equipment to the UPS. Do not power any other equipment from the UPS.